


An Ohmmeter will read ∞ when open/no continuity and will read a Ω value when closed/continuity exists

Verifying a connection



Connection



All connects will be shown w/ a dot.

LAMP




Resistor



Battery



Transformer



Ground



Misc. Symbols

Push Button

Momentary Contact

3 Position Switch Symbols

Sliding Type



Rotary Type



N.O Pushbutton



N.C Pushbutton



2 Position Switch Symbols.


Single Pole Single Throw



Single Pole Double Throw



Double Pole Single Throw



Three Way



4-WAY



Three Position



Three Position Selector

